



Plastics and Resins

[back to list](#)

Product Name:	Polypropylene Resin (F800E)					
Trade Mark:	Sanren Brand					
Alternative Name:						
Molecular formula/Structural Formula:	□					
Production Process:	Liquid phase bulk polymerization process is used for production of the product. The polymer produced is of random copolymer type.					
Properties:	The pellet product is colourless and in the shape of a cylinder with high light transmittance, good slip performance, low heat-sealing temperature, good sealing performance and printability, stress-fracture resistant, excellent chemical stability and insulation as well as fairly good heat-resistance.					
Grade:						
National Standard Grade:	PPR-F-075					
Enterprise Standard Grade:	F800E					
Specifications:	Q/SH 012.07.06-1999 Polypropylene resin					
	No.	Item	Unit	Quality Criteria		
				Premium-grade	1st-grade	On-spec.
	1	Cleanliness	piece/kg <=	0-5	6-10	11-20
	2	Melt flow rate	g/10min	8.0(+1.5)	8.0(+2.5)	8.0(+3.5)
	3	Tensile yield strength	Mpa>=	25.5	25.0	24.5
	4	Outrigger impact strength(23ℓ)	J/m>=	25.0	17.6	15.7
	5	Bending modulus	GPa>=	0.84	0.82	0.78
	6	Ash	%(m/m<=	0.02	0.03	0.04
	7	Yellowness-index	<=	4	4	4
	8	Haze	%<=	2	2	5
	9	Gloss	%>=	86	86	80
	10	Friction coefficient	%<=	0.6	0.8	1.0
	11	Fish-eye	Piece/1520cm ²	0-1.0	1.1-3.0	3.1-5.0
		0.8mm		0-10	11-20	21-30
		0.4mm	<=			
						17108
Scope of Application:	Casting film					
Major Applications:						
Process Method:	Extrusion moulding					
Packing:	Heavy duty PE bag as inner packaging and PP woven bag as outer packaging. Each bag has a net weight of 25 kg.					
Packing Size:	Converted dimension 550mm×850mm,or big package.					
Storage:	The product should be stored in a dry, well ventilated warehouse. To avoid direct sunlight, the product should not be stored in the open air.					
Transportation:	By means of truck, vessel or train. During transportation the product should not be exposed to the sunlight and rain. Neither should the product be mixed with contaminants. There should be no heavy bump or unloading by throwing the bags.					
Safety Precautions:	1. Be away from fire and heat sources. 2. Should not be stored or transported together with chemicals and inflammables. 3. Warehouse must be equipped with extinguishers or fire-fighting device. 4. Water, carbon dioxide, dry powder or 1211 can be used as extinguishers for the product.					

